

MERIDIAN
19 SEPT
THIS PLAT
BOUNDARY
FEDERAL

PLAT RECORDED
IN PLAT BOOK 22 PAGE 353
THIS 7 DAY OF Oct 1986
Dean Jones, Deputy

NEAREST ADDRESS:
45 FORTSON DRIVE

I certify I have examined the current FIA official flood hazard map and found referenced lot is not in an area having special flood hazards.


Ray N. Woods
Georgia Registered Land Surveyor No. 2049

BOOK 672 PAGE 346

- IPF - Iron Pin Found
- IPS - Iron Pin Set
- ⊗ - Traverse Point

I hereby certify, this plat is a correct representation of the land platted and has been prepared in conformity with the minimum standards and requirements of law.

Ray N. Woods
Georgia Registered Land Surveyor No. 2049



RAY N. WOODS & CHRISTINE BERDING			
DECATUR FEDERAL SAVINGS & LOAN ASSOC			
COUNTY	STATE	DATE	
CLATSOP	GA	9-24-84	
PLAT BOOK	CLOSURE	ANGLE CLOSURE	DRAWN BY
			MICHAEL W.
SURVEYED BY			FIELD BOOK
RAY N. WOODS			456

CLOSURE

Oh